## SAGAR CEMENTS LIMESTONE MINE - 2 OF SAGAR CEMENTS LIMITED

Pedaveedu Village, Mattampally Mandal, Suryapet District.

AMBIENT AIR QUALITY MONITORING REPORTS (July - Sept. 2021)

SI No	Location	Near Drilling	Near Loading	Haul Road Cross	Haul road exit of MLB	Near Haulage road	Near Mines Office	Gundlapally Village	Pedaveedu Village	Ramachandrap uram Village	LIMITS	PROTOCOL
	Date of Sampling	20.09.2021		15.09.2021		20.09.2021		19.09.2021			***	***
		Core Zone Buffer Zone										
1	Total time of monitoring		24 Hours									***
2	Average flow rate ( cum/min)	1.07	1.10	1.05	1.12	1.12	1.05	1.02	1.07	1.12	***	***
3	Particulate matter concentration (µg/m³)-PM10	72	76	72	65	69	56	63	61	47	<100	IS-5182 (Part-23)
4	Particulate matter Concentration(µg/m³)-PM2.	28	30	27	23	26	18	23	20	15	<60	NAAQMS/ 36/2012-13
5	Sulphur dioxide (So2) Concentration(µg/m³)	10	13	13	10	12	09	10	07	07	<80	IS-5182 (Part-2)
6	Nitrogen dioxide (No2)  Concentration(µg/m³)	24	27	26	22	25	21	18	19	16	<80	IS-5182 (Part-6)
7	CO Concentration (ppm)	<1	<1	-	-	<1	<1	<1	<1		<2	IS-5182 (Part-10)